



Ax55



Bx55



Cx12



Dx12



Ex16



Fx40






Gx1




Hx2




Ix4




STEP-1




STEP-2




STEP-3




STEP-4



STEP-5




STEP-6




X3


STEP-8




STEP-9




STEP-10




STEP-11




STEP-12




STEP-13




STEP-14




STEP-15



STEP-16



STEP-17



STEP-18

